

# Release notes

## Summary of updates up to release 1.6

---

### RELEASE 1.6 (Oct 2011)

#### Enhancements and new features

- Added new scenes model (scenes as editable sequences of actions), including support for time delays
- Added support for precise positioning in blind controls
- Catalan language now supported
- The timer channel list now shows visually which channels are enabled
- Increased max number of maps and zones for HC2, HC2L
- Several optimizations in the web interface, with improved support for Android smart phones
- Internationalization of the configuration software installer

#### Bug fixes

- Alarm bypass status was not being reset when a new project was uploaded. Fixed.
  - When adjusting ring volume with the +/- buttons, the volume was not being saved correctly. Fixed.
  - Fixed issue where the project size would grow each time a map image was selected and discarded.
- 

### RELEASE 1.5 (Jul 11, 2011)

#### Enhancements and new features

- Added IP camera visualisation functionality (HC2, HC2L only)
- Improved icon catalog: added new page and action icons
- Added support for "startup scene" (a scene to be run at startup)
- Added new comm objs to indicate that presence simulation is running
- Added support for door open function in Helios IP when there is no ongoing call ("HTTP open door") (HC2, HC2L only)
- The configuration software now allows to assign names to all project elements
- The configuration software now allows reordering of zones, pages, and components within the project tree

#### Bug fixes

- Fixed virtual keyboard painting when text field is empty (HC1)
  - Fixed deadlock when entering energy saving mode while certain dialogs were open (HC2, HC2L)
  - When presence simulation was running, no distinction was being made between day and night periods. Fixed.
- 

### RELEASE 1.4.4

#### Enhancements and new features

- Added support for second door in Mobotix T24 door stations
- Ring and conversation volume can now be adjusted separately
- Improvements in audio configuration dialog
- The configuration software now allows preconfiguration of door stations' IP settings

#### Bug fixes

- Fixed handling of 14 byte comm objs
  - Fixed initial value of target temperature for internal thermostat
- 

### RELEASE 1.4.3

#### Enhancements and new features

- Added support for new Iddero HC2L-KNX touch panel

**Bug fixes**

- Fixed automatic incoming call termination if not picked up after 15 seconds
- 

**RELEASE 1.4.2**

**Enhancements and new features**

- Added new UI component for RGB dimmer control
- Added support for TS-N1P external temperature sensor (HC2)
- The configuration software now prompts for confirmation before exit

**Bug fixes**

- Fixed upper and lower limits in regulation bar
  - Fixed loading of projects using an external KNX temperature sensor
- 

**RELEASE 1.4.1**

**Enhancements and new features**

- Added option to force touch screen recalibration from web interface in installation mode
  - Several improvements to make it easier to enter installation mode
  - Internal audio amplifier automatically turned off when not in use
- 

**RELEASE 1.4**

**Enhancements and new features**

- Added support for new Iddero HC2-KNX touch panel
- Added video door phone function
- Added option to enable / disable automatic mode for HVAC control